

(1/33)




Fig. 2A





FIG. 3A



(3/33)





Fig.3D

1030242 2420001

[illegible]

**THE**




Fig.4D  
section A-A




Fig.4E  
section B-B

(6/33)





Fig.4F  
section A-A

(7/33)



(8/33)




Fig. 5D  
section C-C





Fig. 5E  
section D-D



(9/33)

1000044-10201



(10/33)




Fig.6B




Fig.6A

Fig.6C

1000044-10001

Fig.6E

Fig.6F

Fig. 6D

(12/33)





Fig.6F

(13/33)



(14/33)




Fig. 7D  
section E-E





Fig. 7E  
section F-F

(15/33)



$$\begin{aligned} \frac{c_0}{2} &= 1 & p &= 0, 0.25, 0.5 \\ c_1 &= 0 \\ c_2 &= 0 & q &= 0, 0.25, 0.5 \\ c_3 &= p+q \end{aligned}$$

Fig.7F

(16/33)




Fig. 7G




Fig. 7H

section H-H (G-G)




Fig. 7I

section I-I (G-G)

10242 030102



(17/33)





Fig.7 J  
section H-H (G-G)

(18/33)



$$\begin{aligned}
 \frac{C_0}{2} &= 1 & p &= 0, 0.25, 0.5 \\
 C_1 &= 0 & q &= 0, 0.25, 0.5 \\
 C_2 &= p+q
 \end{aligned}$$

Fig.7K

(19/33)




Fig.7L

(20/33)





Fig.7M

(21/33)



(22/33)




Fig.8C

(23/33)




Fig.9B

FIG.9C

Fig.9A

10030242 102201 2420001

(24/33)




Fig.9C



(25/33)





Fig.9D

(26/33)



(27/33)





Fig.10C

(28/33)



(29/33)





Fig.11C

(30/33)



(31/33)





Fig.12C

(32/33)





(33/33)




Fig.14